CANAL

2732
S.L.

S/T
1267

122E
122D
120B
118B
122C
122B
13804
13803
124C
35478
37462
JLN PARI BURONG
114A
112A
110A
108A
110
108
126B
124B
130B
128B
32B
32C
13802
118A
116A
114
112
122A
120A
118
116
122
120
37463
JLN PARI BURONG
13805
126A
124A
128A
130A
126
124
109
111
113
115
117
1269
DRAIN RESERVE
1848
13806
134A
132A
138A
136A
142A
140A
142
65
63
61
59
57
55
53
51
49
47
JLN PARI DEDAP
PEAKVILLE WALK
PEAKVILLE GROVE
16
14
12
10
8
6
4
2
1
3
5
7
9
11
13
15
17
19
21
20
18
16
14
12
10
8
6
4
2
47
45
43
41
39
42
40
38
36
34
32
30
37
651
S.L.
P.G.
209
S.L.(HDB)
948
548

BD 018

IMPORTANT NOTE

Information contain on this map is Confidential-StarHub Cable Vision Ltd Property. It is not to be copied or reproduced in any form nor is not to be transmitted to any other parties other than to whom StarHub Cable Vision Ltd has given express written authority.

Information shown are underground services only and all distance shown are approximated. Exact distance must be verified on site.

Please note that cable positions indicated are not drawn to scale and their exact locations must be determined on site.

Information is accurate at time of printing.

LEGEND
AMPLIFIER PANEL BOX
TAP BOX
PEDESTAL BOX TV1200
PEDESTAL BOX TV60
100MM PIPE
40MM PIPE
TRUNKING/CONDUIT
TRUNKING/CONDUIT
COAXIAL CABLE IN MANHOLE
LEAD-IN PIPES

...\working\dgn\bd018_sla.dgn Jun. 12, 2008 15:49:32

...FARMER
...Validity Date:
12 DEC 2008
...the accuracy or completeness of the ... which may ... to ... We disclaim any ... be caused to or suffered by ... directly or indirectly as a result ...
StarHub Cable Vision Ltd