

# **HOCK LIAN BUILDING CO. PTE LTD**

BLK 721 CLEMENTI WEST STREET 2 #01-110 SINGAPORE 120721

TEL: 65-63161609 FAX: 65-67791181

EMAIL: hocklian@singnet.com.sg

## **TRIAL PIT TEST**

**FOR**

**LAND PARCEL NO. 6**

**AT**

**SOMME ROAD**

Client/Owner : Singapore Land Authority  
Conducted by : Hock Lian Building Co. Pte Ltd  
Inspected & Certified : Millenniums Consultants  
Date : 26 September 2007

## **CONTENTS**

	<b><u>Page</u></b>
<b>1 INTRODUCTION</b>	<b>1</b>
<b>2 SCOPE OF WORK</b>	<b>2</b>
<b>3 TRIAL PIT LOCATION PLAN</b>	<b>3</b>
<b>4 CABLE DETECTION REPORT</b>	<b>4</b>
<b>5 FINDINGS</b>	<b>6</b>
<b>6 CONCLUSION</b>	<b>7</b>

**REPORT:**

**TRIAL PIT TEST FOR LAND PARCEL NO. 6 AT SOMME ROAD**

Client : Singapore Land Authority  
Location : Somme Road  
Land Parcel : 06  
Prepared by : Millenniums Consultants (PE)

**1 INTRODUCTION**

Trial pit excavation was carried out for Land Parcel No. 6 at Somme Road for the purpose of visual inspection for soil condition and possibility of illegal dumping.

A total of 1 trial pit was excavated for approx. 365.80m<sup>2</sup> of land at location shown in the Trial Pit Location Plan (as attached). Prior to the excavation, cable detection has been carried out to confirm location of the services as this is a built up area.

The work was carried out according to the instructions given by Singapore Land Authority.

## 2 SCOPE OF WORK

2.1 The purposes of this Report were:


- a. To explore the sub-surface conditions of the Proposed Development area and to provide general soil data relating to the Project.
- b. To determine the existence of any illegal dumping found on site.
- c. To observe the water table level.

2.2 Description of Trial Pit Excavation

The sequence of works was as follows:

- Site Clearance carried out by excavator.
- Trial Pit locations were determined by pegging on site.
- The trial pits in the size of 1.5m x 1.5m x 3m depth were excavated using hydraulic excavator Kobelco 03 series SK60 and Mini excavator.
- Timber barriers with red and white safety tape were putted up around the pits for safety reason.
- Photographs and visual inspections were carried out by PE.

### 3 TRIAL PIT LOCATION PLAN



#### 4 CABLE DETECTION REPORT

#### FORM NCD

Deputy Director  
Earthworks Monitoring &  
Cable Protection Section  
Network Management Division  
SP PowerGrid Ltd  
25 Pasir Panjang Road  
Singapore 117536

(This form is to be submitted with site plans indicating the detection zone clearly before the commencement of cable detection work.)

FAX NO: 64759400  
DID NO: 64700604/5

#### NOTIFICATION OF COMMENCEMENT OF CABLE DETECTION WORK

I, the undersigned, intend to carry out cable detection work. The particulars are as follows:-

- 1 Location of cable detection work : SOMME ROAD
- 2 Particulars of contractor/client : HOCK LIAN BUILDING CO.  
Company / Person-in-charge : MR QUEK KAI YONG  
Address : BK 721 CLEMENTI WEST ST2 # 01-22110. S120721  
Tel No: 63161809. Fax 67791181 Pager No. : \_\_\_\_\_
- 3 Principal : SLA Dept/Section : \_\_\_\_\_
- 4 Date cable route drawings obtained (LCDW to note mandatory requirement) : 26/9/07
- 5 Date of cable detection to be carried out : 26/9/07
- 6 Voltage Level of the cable in the vicinity? No SPPA's cable / LV/HT
- 7 Proposed dates for earthworks :  
Start : 26/9/07 Finish : 30/9/07
- 8 Purpose of earthworks : TRIAL PIT (1NO)

I shall prepare and issue to my client a set of cable detection records and keep EMCP informed of any changes in the above particulars by fax. I will also remind my client to submit the Notice for Commencement of Earthworks (NCE) if there are High Voltage cables within the vicinity.

[Signature]  
Signature

SIM YONG KWEE  
Name of Licensed Cable Detection Worker




Date : 26/9/07

Licence No. : 89-0108

Tel No. : \_\_\_\_\_

Mobile No. : 98184225

\*Delete where applicable.  
(Revision Feb 2006)



## 5 FINDINGS



Location: Land Parcel No. 6 at Somme Road

Trial Pit No: 001

Size: 1.5m length x 1.5m width x 3m depth

Original State: Land with maintained cow grass turfing

Soil Condition up to 3 metres: The following materials were not found:

- material from sump
- large timber pieces
- tree trunks
- rubber tyres
- materials susceptible to spontaneous combustion
- organic municipal waste
- other industrial and domestic refuse
- soil of liquid limit exceeding 70 and/or plasticity index exceeding 35
- materials having moisture content greater than the maximum permitted for such materials in the Contract, unless otherwise permitted by the Superintending Officer
- rock, which are hard material whose geological nature is to be regarded as such and individual boulders exceeding 0.20m<sup>3</sup> or other masses of hard natural material which necessitates the use of blasting or approved pneumatic tools for their removal.

Water Table: No sign of high water table

## 6 CONCLUSION

At the only trial pit that we have inspected, we found no signs of illegal dumping and water table. The soil condition is good.

However, clay composition is found at approx 0.5metre below ground level.

Should there be any question regarding our work, we would be pleased to discuss them with you.

The Contents as described in this report for Trial Pit Test for Land Parcel No. 6 at Somme Road are hereby certified to be correct.



---

Endorse by Professional Engineer